


Risk treatment

Risk treatment is one step in the risk management process, aiming to reduce the level of risk.

- 1 Geotextile lining
- 2 Slope drainage
- 3 Rock bolting
- 4 Retaining wall
- 5 Slope reprofiling
- 6 Slope revegetation



A The landslide hazard

